



中国民用航空局
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

维修许可证
MAINTENANCE ORGANIZATION CERTIFICATE

编号/No. F03300475

单位名称/NAME OF ORGANIZATION:

RATIER FIGEAC

单位地址/BUSINESS ADDRESS:

Avenue Ratier 46100 Figeac, France

经审查，该单位符合中国民用航空规章第 145 部的要求，可以从事如下类别的维修工作：
Upon finding that the organization complies with the requirements of **CHINA CIVIL AVIATION REGULATION(CCAR)** Part 145, the above organization is adequate to accomplish maintenance of the following ratings:

Propeller Maintenance
Component Maintenance
Specialized Service

- ☆ -

本许可证除被放弃、暂停或吊销，在下述期限内将一直有效。
This certificate, unless cancelled, suspended, or revoked, shall continue in effect until:

2024-12-31

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2007-12-17

再次颁发日期/DATE REISSUED:

2023-05-07





中国民用航空局
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

许可维修项目

LIMITATION OF MAINTENANCE ITEMS

限定/LIMITATION:

对第 F03300475 号许可证所列维修类别限定如下地点和项目:

Location and items set forth on Maintenance Organization Certificate No. F03300475 is/are limited to the following:

LOCATION: FIGEAC

Repair, Modification, Overhaul of the following Propeller: 247F-1/-1E/-3 Series; 568F-1/-5/-7 Series; 14SF series.

Inspection, Repair, Overhaul and Modification of following components:

Flight Controls (ATA-27): Limit to 2700 Flight Control System; 2701 Control Column Section; 2710 Aileron Control System; 2711 Aileron Tab Control System; 2720 Rudder Control System; 2721 Rudder Tab Control System; 2722 Rudder Actuator; 2730 Elevator Control System; 2731 Elevator Tab Control System; 2740 Stabilizer Control System; 2741 Stabilizer Position Indicating; 2742 Stabilizer Actuator; 2750 TE Flap Control System; 2751 TE Flap Position Ind. System; 2752 TE Flap Actuator; 2761 Drag Control Actuator; 2770 Gust Lock/Damper System; 2770 LE Slat Control System; 2797 Flight Control System Wiring.

Ice and Rain Protection (ATA-30): Limit to 3020 Air Intake Anti/De-Ice System.

Landing Gear (ATA-32): Limit to 3242 Brake; 3251 Steering Unit.

Doors (ATA-52): Limit to 5210 Passenger/Crew Doors; 5220 Emergency Exits; 5240 Service Doors.

(To Be Continued)

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2007-12-17

再次颁发日期/DATE REISSUED:

2023-05-07





中国民用航空局
CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

许可维修项目

LIMITATION OF MAINTENANCE ITEMS

限定/LIMITATION:

对第 F03300475 号许可证所列维修类别限定如下地点和项目:

Location and items set forth on Maintenance Organization Certificate No. F03300475 is/are limited to the following:

LOCATION: FIGEAC(Continued)

Inspection, Repair, Overhaul and Modification of following components:

Fuselage (ATA-53): Limit to 5311 Fuselage Main, Frame; 5350 Aerodynamic Fairings.

Propellers (ATA-61): Limit to 6113 Propeller Spinner Section; 6121 Propeller Synchronizer Section; 6130 Propeller Braking.

Rotor Drive(s) (ATA-63): Limit to 6321 Main Rotor Brake.

Engine Controls (ATA-76): Limit to 7603 Power Lever.

Detail as listed in CAAC maintenance capability list.

Specialized Service

1). Fluorescent Dye Penetrant Inspection; 2). Ultrasonic Inspection; 3). Eddy Current Inspection 4). Tap Test; 5). Magnetic Particle Inspection.

- ☆ -

局长授权/ FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/POSITION:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2007-12-17

再次颁发日期/DATE REISSUED:

2023-05-07

